## Approved For Release 2002/07/31 - CIA-RDP61-00763A000200130039-7

DPD 8025-59

30 November 1959

MEMOFARDIM FOR: Chief, Materiel Branch

SURJECT : Malfunction Report for Movember 1959

- 1. Detachment B reported a malfunction on Mission 3652, 19 Movember 1959. The plastic insulator insert for the cap of the Capstan motor on the System VI Slave Recorder slipped out of position and interferred with proper motor operation. The inserts will be removed in the future and the inside of the caps will be sprayed with Erylon Insulating paint.
- 2. Detachment C reports a failure in the return ferry flight of Mission 60%6. The Master and A. C. generator switches were inadvertently thrown at altitude which applies full power to the cold equipment and resulted in the failure of the System III. An examination of the tape indicates a failure of the third local oscillator board.

Chief, Communications Section
DPD-DD/P

Distribution:

0 & 1 - Addressee

1 - File

1 - Chrono

LY- RI

CHV/WWB/sjl

30 November 1959

25X1A